

Paradise Water Report
November 16, 2019

Since the last report all sampling results have been satisfactory. Repairs were needed to replace a pressure switch that operated one of the booster pumps and a captive air tank that had a failed bladder. The tank was surcharged which made it ineffective in reducing the water hammer that may occur when the pumps start and stop.

The scope of work included: Isolate the tank and switch, drain tank, remove tank, remove and replace pressure switch, install new tank, normalize system, verify proper operation and haul off old tank.

The repairs were made by NW Water and cost \$1411.44 including sales tax.

We will be accepting proposals from landscaping firms to mow and maintain the well site for 2020. We should have an idea who we will use before we need to mow in the spring.

Please see the treasurer's report for the water system financial status.

This concludes my report please report suspected leaks and fix those running toilets.

Respectfully submitted

Tom Moore