

Water System Report  
September 18, 2021

The Water system did not experience any major issues since the last report. There was a coliform presence detected during the hot weather but subsequent testing did not detect a presence so it could have been a sampling error or other undetermined anomaly. These detections are not unusual and when undetected through subsequent sampling of the original site, two points one upstream one downstream and any wells that were running at the time no further action is required.

The propane tank is about 60-65% full and Ferrell gas will not refill until the level drop to 40% or less. We are not using any propane but for the weekly test run. Power Systems NW will service the generator in October.

Jose Raymundo will be cleaning up the well sites as soon as the current rains stop sometime next week.

I still have to get the hoses for blowing off the hydrants, nor have I been able to meet with a painting contractor about the pump house piping. I have a call into one but have been playing phone tag. It should happen next week I hope.

Respectfully submitted

Tom Moore  
Water System Co-Chair